

SIRGM1C Applications

Compatible Vehicles

		Recommended Cables				
		If Factory XM, or XM pre-wiring, is Present- Use the following Harness	Connects At	Factory XM tuner location	If Vehicle is not pre-wired for XM use the following Harness	Connects At
Buick						
2005-06	Allure	Factory SDAR Interface Cable	XM Tuner Location	Left Rear Quarter Panel	N/A	
2004-05	LeSabre	Factory SDAR Interface Cable	XM Tuner Location	Left Rear Quarter Panel	N/A	
2004-06	Rainier	Factory SDAR Interface Cable	XM Tuner Location	Behind Glovebox	T-Harness	Radio
2003-06	Rendezvous	Factory SDAR Interface Cable	XM Tuner Location	Behind Glovebox	T-Harness	Radio
2005-06	LaCrosse	Factory SDAR Interface Cable	XM Tuner Location	Left Rear Quarter Panel	T-Harness	Radio
2005-06	Terazza	Factory SDAR Interface Cable	XM Tuner Location	Left Side of Dash above Steering Column	T-Harness	Radio
Cadillac						
2004-06	CTS**	Factory SDAR Interface Cable	XM Tuner Location	On rear deck left side	N/A	
2003-06	Escalade/EXT/ESV	Factory SDAR Interface Cable	XM Tuner Location	Behind Glovebox	T-Harness	Radio
2003-05	DeVille	Factory SDAR Interface Cable	XM Tuner Location	Behind Rear seat	N/A	
2004-06	SRX	Factory SDAR Interface Cable	XM Tuner Location	Right rear quarter panel	N/A	
2005-06	XLR	Factory SDAR Interface Cable	XM Tuner Location	Between seats	N/A	
Chevrolet						
2003-06	Avalanche	Factory SDAR Interface Cable	XM Tuner Location	Behind Glovebox	T-Harness	Radio
2004-05	Blazer				T-Harness	Radio
2003-05	Cavalier	Factory SDAR Interface Cable	XM Tuner Location	On rear deck in center	T-Harness	Radio
2005-06	Colorado	Factory SDAR Interface Cable	XM Tuner Location	Behind Glovebox	T-Harness	Radio
2005-06	Corvette	Factory SDAR Interface Cable	XM Tuner Location	Driver side rear panel (above wheel well)	T-Harness	Radio
2005-06	Equinox	Factory SDAR Interface Cable	XM Tuner Location	Left Rear Quarter Panel	T-Harness	Radio
2003-05	Express Van				T-Harness	Radio
2003-05	Impala	Factory SDAR Interface Cable	XM Tuner Location	Right rear quarter panel	T-Harness	Radio
2003-05	Monte Carlo	Factory SDAR Interface Cable	XM Tuner Location	Right rear quarter panel	T-Harness	Radio
2004	S-10				T-Harness	Radio
2003-06	Silverado/HD	Factory SDAR Interface Cable	XM Tuner Location	Behind Glovebox	T-Harness	Radio
2004-06	SSR				T-Harness	Radio
2003-06	Suburban	Factory SDAR Interface Cable	XM Tuner Location	Behind Glovebox	T-Harness	Radio
2003-06	Tahoe	Factory SDAR Interface Cable	XM Tuner Location	Behind Glovebox	T-Harness	Radio
2003-06	Trailblazer	Factory SDAR Interface Cable	XM Tuner Location	Behind Glovebox	T-Harness	Radio
2005-06	Uplander	Factory SDAR Interface Cable	XM Tuner Location	Left Side of Dash above Steering Column	T-Harness	Radio
2003-05	Venture	Factory SDAR Interface Cable	XM Tuner Location	Left Side of Dash above Steering Column	T-Harness	Radio
GMC						
2005-06	Canyon	Factory SDAR Interface Cable	XM Tuner Location	Behind Glovebox	T-Harness	Radio
2003-06	Denali/Denali XL	Factory SDAR Interface Cable	XM Tuner Location	Behind Glovebox	T-Harness	Radio
2003-06	Envoy	Factory SDAR Interface Cable	XM Tuner Location	Behind Glovebox	T-Harness	Radio
2004	Jimmy				T-Harness	Radio
2004	S-15/Sonoma				T-Harness	Radio
2003-05	Savana Van				T-Harness	Radio
2003-06	Sierra/Sierra Denali	Factory SDAR Interface Cable	XM Tuner Location	Behind Glovebox	T-Harness	Radio
2003-06	Yukon/Yukon XL	Factory SDAR Interface Cable	XM Tuner Location	Behind Glovebox	T-Harness	Radio

**Note: The Cadillac CTS requires a modification to the Factory SDAR Interface Cable. Pin 3 (White) and Pin 10 (Black) must be switched. See the Cadillac CTS Installation Modification sheet included with the SIRGM1C for more details.


SIRGM1C Applications

Recommended Cables

Compatible Vehicles


Compatible Vehicles		If Factory XM, or XM pre-wiring, is Present- Use the following Harness	Connects At	Factory XM tuner location	If Vehicle is not pre-wired for XM use the following Harness	Connects At
Hummer						
2004-06	H1	Factory SDAR Interface Cable	XM Tuner Location	Unavailable	T-Harness	Radio
2003-06	H2	Factory SDAR Interface Cable	XM Tuner Location	Behind Glovebox	T-Harness	Radio
2006	H3	Factory SDAR Interface Cable	XM Tuner Location	Behind Glovebox (Remove Radio to access)	T-Harness	Radio
Isuzu						
2003-06	Ascender	Factory SDAR Interface Cable	XM Tuner Location	Behind Glovebox	T-Harness	Radio
Oldsmobile						
2003-04	Alero	Factory SDAR Interface Cable	XM Tuner Location	RF of passenger compartment	T-Harness	Radio
2003-04	Bravada	Factory SDAR Interface Cable	XM Tuner Location	Behind Glovebox	T-Harness	Radio
2003-04	Silhouette	Factory SDAR Interface Cable	XM Tuner Location	Left Side of Dash above Steering Column	T-Harness	Radio
Pontiac						
2003-05	Aztek	Factory SDAR Interface Cable	XM Tuner Location	Behind Glovebox	T-Harness	Radio
2003-05	Bonneville	Factory SDAR Interface Cable	XM Tuner Location	Left Rear Quarter Panel	N/A	
2003-05	Grand Am	Factory SDAR Interface Cable	XM Tuner Location	Left Rear Quarter Panel	T-Harness	Radio
2004-06	Grand Prix	Factory SDAR Interface Cable	XM Tuner Location	RF of passenger compartment	T-Harness	Radio
2003-05	Montana	Factory SDAR Interface Cable	XM Tuner Location	Left Side of Dash above Steering Column	T-Harness	Radio
2005-06	Montana SV6	Factory SDAR Interface Cable	XM Tuner Location	Left Side of Dash above Steering Column	T-Harness	Radio
2003-05	Sunfire	Factory SDAR Interface Cable	XM Tuner Location	On rear deck in center	T-Harness	Radio
2004-06	Vibe	Factory SDAR Interface Cable	XM Tuner Location	Right rear quarter panel	T-Harness	Radio
Saab						
2005-06	9-7X	Factory SDAR Interface Cable	XM Tuner Location	Behind Glovebox	T-Harness	Radio
Saturn						
2005-06	Relay	Factory SDAR Interface Cable	XM Tuner Location	Left Side of Dash above Steering Column	T-Harness	Radio

Factory SDAR Interface Cable



Used to replace the factory XM tuner module

T-Harness Interface Cable



Used when the vehicle is not pre-wired for satellite radio

Vehicles must be GM Class-2 Bus compliant and the headunits must have a BAND button or Direct XM selection to be compatible. Some of the 2006 vehicles listed may have transitioned to the GM -LAN bus mid year - which are not compatible with the SIR-GM1.

The factory XM antenna is not compatible with the SIR-GM1. Please use the Sirius antenna supplied with the product